



Horatia House and Leamington House

Cladding Removal

Progress Report 9th October 2017



Site Plan



Horatia House



Figure 1 - East Elevation cladding removed to 6th floor, mast climber installed to 1st floor level



Figure 2 - East Elevation cladding removed to 6th floor, mast climber installed to 1st floor level



Figure 3 - Mast climber being installed to south elevation



Figure 4 - North elevation



Figure 5 - West elevation, cladding removed to the $\textbf{4}^{\text{th}}$ storey



Figure 6 - West elevation, cladding removed to the $\mathbf{4}^{\text{th}}$ storey



Figure 7- Example of a completed foundation to enable the mast climber installation



Figure 8 - Restricted car parking in car park to west of block



Figure 9- Use of carpark to west of building for contractor storage



Figure 10 - Use of carpark to west of building for contractor storage

Leamington House



Figure 11 - Scaffold fan erected to main entrance, east elevation



Figure 12 - East elevation, cladding partially removed to the 5th floor



Figure 13 - East elevation cladding partially removed to 5th floor



Figure 14 - West elevation, 50% of cladding removed to 7^{th} storey, remainder of cladding removed to 4^{th} storey



Figure 15- Scaffold fan install to north elevation



Figure 16 - Scaffold fan installed to south elevation