

Asset Type: Block of Flats, Bungalow, Flat, House, House in Multiple Occupat...

Construction Type: (Blank), Acquired Traditional, BISF, Bison, Concrete ring beam

Repair Keywords: Damp and Mould - Condensation, Damp and Mould - External Leaks, Damp and Mould - Internal Leaks, Damp and Mould - Rising Damp, No Damp/Mould Keyword

Repair Status: Repair Closed, Repair Open


Surveyor Appointments: Building Surveyor Appointments, No Building Surveyor Appointment

### Quarterly Performance

Q1 2023	Q2 2023	Q3 2023	Q4 2023
4	20	289	86
Repairs where First Appointment is within 14 Days of First Contact Date			
75.0%	80.0%	83.7%	97.7%

### Overall Performance

Total Repairs	Completed Repairs	Open Repairs
403	154	249
Awaiting Call Back	Total Costs	Average Cost
153	£253.59K	£728.61



Asset ID	Full Address	Asset Type	Repair Status	Repair ID	Repair Keywords	Repair E2E (days)	First Contact Date	Last Repair Completed Date	Surveyors Appointments	Appointments	Cancelled Appointments	Total Cost
----------	--------------	------------	---------------	-----------	-----------------	-------------------	--------------------	----------------------------	------------------------	--------------	------------------------	------------