








Option 1 – Reinstate the existing memorial benches on the new promenade intermixed with new



Not recommended:

- Mismatch of street furniture (new and old) leading to a disjointed and cluttered promenade – conflicts with the project objective of creating a "world-class seafront"
- Existing benches are in varying degrees of condition some would not be suitable for reinstatement





Option 2 – Relocate the current plaques on the nearest new bench to the current bench location








Recommended:

- > Plaques remain close to the owners chosen location
- ➤ New benches can accommodate 3 4 plaques
- > Plaques re-sited on benches with a +25 year design life





Frontage 4 – Southsea Castle Existing: 20 benches / 25 plaques New: 14 benches / capacity for up to 56 plaques





Frontage 4 central section - 15 existing benches replaced with 4 new benches and capacity for all plaques